UP

BAG DUMPING STATION

BAG DAMPING STATION

UNLOADING AREA

RM

1 BAY

2 BAY

3 BAY

4 BAY

SILOS

SILOS

TANK FARM AREA

TANK FARM AREA

CAUTION!

ट्रक मूवमेंट
TRUCK MOVEMENT

कार्यरत उपकरणों से हाथों को दूर रखें।
KEEP FEET & HANDS CLEAR OF MOVING EQUIPMENT

एम एच ई कार्यरत
MHE OPERATIONS

भारी कार्यरत
HEAVY LOAD MOVEMENT

LOGO

गाड़ी सुरक्षित खड़े करने हेतु सुरक्षा चिह्न

REPORT ADVERSE EVENTS IMMEDIATELY

H.S. DIESEL & FURNACE OIL YARD

एसिड और अल्कली से सम्य कार्य करते समय सुरक्षा साधनों का प्रयोग करें।
FOLLOWING PPE'S MUST BE WORN WHILE HANDLING ALKALI

सुरक्षा जूते पहनें
WEAR SAFETY BOOTS

सुरक्षा दस्ताने पहनें
WEAR SAFETY GLOVES

सुरक्षा चश्मा पहनें
WEAR SAFETY GOGGLE

सुरक्षा शिल्ड पहनें
WEAR SAFETY SHIELD

सुरक्षा अप्रान पहनें
WEAR SAFETY APRON

DIESEL STORE
DAY TANK NO - 1

NO HOT WORK WITHOUT PERMIT

CAUTION !

UTILITY BUILDING

AIR COMPRESSOR ROOM

CHILLING PLANT

BOILER HOUSE

कार्य करते समय सुरक्षा साधनों का प्रयोग करें।
FOLLOWING PPE'S MUST BE WORN WHILE ON WORK

सुरक्षा जूते
SAFETY SHOES

सुरक्षा इंयर प्रोटेक्शन
EAR PROTECTION

CAUTION! HOT SURFACE

WARNING! MIND YOUR HEAD

MATCH LINE 'A–A' REFER DWG. No.–

PCC ROOM

MCC/PCC ROOM

WEAR REQUIRED PPE

आवश्यक पी पी ई जरूर पहनें।

CAUTION!

PRECAUTIONS TO BE TAKEN WHILE WORKING ON ELECTRIC PANEL / SWITCH GEAR.

- ISOLATE POWER OF TH EQUIPMENT BEFORE STARTING JOB.
- USE PROPER INSULATED, MACHINES, SWITCH GEARS.
- USE PROPER HAND GLOVES.
- DO NOT STAND ON WET / MOIST SURFACE WHILE WORKING ON ELECTRICAL PANELS
- DO NOT BY PASS INTERLOCKS.

CAUTION ! ELECTRICAL HAZARD

ELECTRICAL PANEL DG SETS

FUEL TANK